





CONTENTS

Surface Mount 01 Lighting Assembly



(x2) 8-32 Screw 	(x5) Wago Connector 	(x1) Driver 
Glass diffuser 	(x2) Toggle anchor On 240V fixtures only 	
	(x2) Wood screw On 240V fixtures only 	(x2) Long 8-32 screw On 240V fixtures only 
		(x2) Metal screw On 240V fixtures only 


SAFETY INFORMATION

Suitable for dry or damp locations.
The light source contained in this luminaire shall only be replaced by the manufacturer or his service agent or a similar qualified person.

Laddi Surface Mount 02 | INSTALLATION

Note: Please contact a licensed electrician for installation. Ensure power is off during installation.


01. Unscrew the threaded collar (A) from the star base (B) to release the LED with crossbar assembly (C).



Laddi Surface Mount 02 | INSTALLATION

Note: Please contact a licensed electrician for installation. Ensure power is off during installation.

02. Bring the LED driver (D) to the J-box(E). then make the lead wire connection with the provided 2-port wagos (F).
03. Optional, make the dimming wire connection with the provided 2-port wagos (G).
04. Tuck the LED driver into the J-box, be sure to pull out the green ground wire.
05. Bring the LED with crossbar assembly (C) up to J-box, and make the ground wire connection with provided 2-port wagos (H).
06. Then make the low voltage wire connection with provided 2-port wagos (I).
06. Tuck the wires back into the J-box
06. Secure the crossbar (C) to J-box (E) with the provided two screws (J).
07. Fit the star shaped base (B) onto the LED with crossbar assembly (C), and secure it with the threaded collar (A).



Laddi Surface Mount 02 | INSTALLATION

Note: Please contact a licensed electrician for installation. Ensure power is off during installation.

08. Secure the glass diffuser (K) on to the star shape base (B) by screwing it in clockwise.

